

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077  
 Phone/Fax: (800) 220-3675 / (856) 786-0327  
<http://www.EMSL.com> [cinnaminsonradonlab@emsl.com](mailto:cinnaminsonradonlab@emsl.com)

EMSL Order: 381601096  
 CustomerID: PGCS62  
 CustomerPO:  
 ProjectID:

Attn: **Karen Bowlding**  
**Prince George's County School**  
**13300 Old Marlboro Pike**  
**Upper Marlboro, MD 20772**

Phone: (301) 952-6559  
 Fax: (301) 952-0346  
 Received: 02/09/16 2:15 PM  
 Analysis Date: 2/11/2016  
 Collected: 2/5/2016

Project: **Clinton Grove**

**Clinton Grove**

## Test Report: Radon in Air Test Results

### Samples for EMSL Kit 135858

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229881	Principal's Office	2.1	2/5/2016	2/8/2016	60	40	Customer
381601096-0001			1:56:00 PM	7:15:00 AM			

**Sample Notes:**

229727	Principal's Office	2.5	2/5/2016	2/8/2016	60	40	Customer
381601096-0002			1:58:00 PM	7:16:00 AM			

**Sample Notes:**

**Summary for EMSL Kit 135858** **Average Radon Result: 2.3 pCi/L**

### Samples for EMSL Kit 135853

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229738	Health Room	1	2/5/2016	2/8/2016	60	40	Customer
381601096-0003			1:59:00 PM	7:17:00 AM			

**Sample Notes:**

229714	Health Room	1	2/5/2016	2/8/2016	60	40	Customer
381601096-0004			2:00:00 PM	7:18:00 AM			

**Sample Notes:**

**Summary for EMSL Kit 135853** **Average Radon Result: 1.0 pCi/L**

### Samples for EMSL Kit 135855

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229656	Room 200	0.2	2/5/2016	2/8/2016	60	40	Customer
381601096-0005			2:01:00 PM	7:19:00 AM			

**Sample Notes:**

229647	Room 200	0.3	2/5/2016	2/8/2016	60	40	Customer
381601096-0006			2:02:00 PM	7:20:00 AM			

**Sample Notes:**

**Summary for EMSL Kit 135855** **Average Radon Result: 0.3 pCi/L**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077  
 Phone/Fax: (800) 220-3675 / (856) 786-0327  
<http://www.EMSL.com> [cinnaminsonradonlab@emsl.com](mailto:cinnaminsonradonlab@emsl.com)

EMSL Order: 381601096  
 CustomerID: PGCS62  
 CustomerPO:  
 ProjectID:

Attn: **Karen Bowlding**  
**Prince George's County School**  
**13300 Old Marlboro Pike**  
**Upper Marlboro, MD 20772**

Phone: (301) 952-6559  
 Fax: (301) 952-0346  
 Received: 02/09/16 2:15 PM  
 Analysis Date: 2/11/2016  
 Collected: 2/5/2016

Project: **Clinton Grove**

**Clinton Grove**

### Test Report: Radon in Air Test Results

**Samples for EMSL Kit 135859**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229844	Room 203	0.3	2/5/2016	2/8/2016	60	40	Customer
381601096-0007			2:03:00 PM	7:21:00 AM			

**Sample Notes:**

229675	Room 203	0.2	2/5/2016	2/8/2016	60	40	Customer
381601096-0008			2:04:00 PM	7:22:00 AM			

**Sample Notes:**

**Summary for EMSL Kit 135859 Average Radon Result: 0.3 pCi/L**

**Samples for EMSL Kit 135863**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229709	Room 204	0.1	2/5/2016	2/8/2016	60	40	Customer
381601096-0009			2:05:00 PM	7:23:00 AM			

**Sample Notes:**

229691	Room 204	0.2	2/5/2016	2/8/2016	60	40	Customer
381601096-0010			2:06:00 PM	7:24:00 AM			

**Sample Notes:**

**Summary for EMSL Kit 135863 Average Radon Result: 0.2 pCi/L**

**Samples for EMSL Kit 135820**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229253	Room 208	0.6	2/5/2016	2/8/2016	60	40	Customer
381601096-0011			2:07:00 PM	7:25:00 AM			

**Sample Notes:**

229181	Room 208	0.7	2/5/2016	2/8/2016	60	40	Customer
381601096-0012			2:08:00 PM	7:26:00 AM			

**Sample Notes:**

**Summary for EMSL Kit 135820 Average Radon Result: 0.6 pCi/L**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>[cinnaminsonradonlab@emsl.com](mailto:cinnaminsonradonlab@emsl.com)

EMSL Order: 381601096

CustomerID: PGCS62

CustomerPO:

ProjectID:

Attn: **Karen Bowlding**  
**Prince George's County School**  
**13300 Old Marlboro Pike**  
**Upper Marlboro, MD 20772**

Phone: (301) 952-6559  
 Fax: (301) 952-0346  
 Received: 02/09/16 2:15 PM  
 Analysis Date: 2/11/2016  
 Collected: 2/5/2016

Project: **Clinton Grove****Clinton Grove****Test Report: Radon in Air Test Results****Samples for EMSL Kit 135825**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229376	Room 209	0.6	2/5/2016	2/8/2016	60	40	Customer
381601096-0013			2:09:00 PM	7:27:00 AM			

**Sample Notes:**

229132	Room 209	0.6	2/5/2016	2/8/2016	60	40	Customer
381601096-0014			2:10:00 PM	7:28:00 AM			

**Sample Notes:****Summary for EMSL Kit 135825 Average Radon Result: 0.6 pCi/L****Samples for EMSL Kit 135766**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229889	Reading & Study Skills	1.2	2/5/2016	2/8/2016	60	40	Customer
381601096-0015			2:11:00 PM	7:29:00 AM			

**Sample Notes:**

229809	Reading & Study Skills	1.1	2/5/2016	2/8/2016	60	40	Customer
381601096-0016			2:12:00 PM	7:30:00 AM			

**Sample Notes:****Summary for EMSL Kit 135766 Average Radon Result: 1.2 pCi/L****Samples for EMSL Kit 135831**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229294	Room 308	1.4	2/5/2016	2/8/2016	60	40	Customer
381601096-0017			2:13:00 PM	7:31:00 AM			

**Sample Notes:**

229184	Room 308	1.4	2/5/2016	2/8/2016	60	40	Customer
381601096-0018			2:14:00 PM	7:32:00 AM			

**Sample Notes:****Summary for EMSL Kit 135831 Average Radon Result: 1.4 pCi/L**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>[cinnaminsonradonlab@emsl.com](mailto:cinnaminsonradonlab@emsl.com)

EMSL Order: 381601096

CustomerID: PGCS62

CustomerPO:

ProjectID:

Attn: **Karen Bowlding**  
**Prince George's County School**  
**13300 Old Marlboro Pike**  
**Upper Marlboro, MD 20772**

Phone: (301) 952-6559  
 Fax: (301) 952-0346  
 Received: 02/09/16 2:15 PM  
 Analysis Date: 2/11/2016  
 Collected: 2/5/2016

Project: **Clinton Grove****Clinton Grove****Test Report: Radon in Air Test Results****Samples for EMSL Kit 135864**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229700 381601096-0019	Teachers Resource Room	0.8	2/5/2016 2:15:00 PM	2/8/2016 7:33:00 AM	60	40	Customer

**Sample Notes:**

229591 381601096-0020	Teachers Resource Room	0.8	2/5/2016 2:15:00 PM	2/8/2016 7:33:00 AM	60	40	Customer
--------------------------	------------------------	-----	------------------------	------------------------	----	----	----------

**Sample Notes:****Summary for EMSL Kit 135864 Average Radon Result: 0.8 pCi/L****Samples for EMSL Kit 135822**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229375 381601096-0021	Room 311	1.5	2/5/2016 2:16:00 PM	2/8/2016 7:35:00 AM	60	40	Customer

**Sample Notes:**

229276 381601096-0022	Room 311	1.3	2/5/2016 2:17:00 PM	2/8/2016 7:36:00 AM	60	40	Customer
--------------------------	----------	-----	------------------------	------------------------	----	----	----------

**Sample Notes:****Summary for EMSL Kit 135822 Average Radon Result: 1.4 pCi/L****Samples for EMSL Kit 135846**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229262 381601096-0023	Room 3A Prep	2.8	2/5/2016 2:18:00 PM	2/8/2016 7:37:00 AM	60	40	Customer

**Sample Notes:**

229128 381601096-0024	Room 3A Prep	2.6	2/5/2016 2:19:00 PM	2/8/2016 7:38:00 AM	60	40	Customer
--------------------------	--------------	-----	------------------------	------------------------	----	----	----------

**Sample Notes:****Summary for EMSL Kit 135846 Average Radon Result: 2.7 pCi/L**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077  
 Phone/Fax: (800) 220-3675 / (856) 786-0327  
<http://www.EMSL.com> [cinnaminsonradonlab@emsl.com](mailto:cinnaminsonradonlab@emsl.com)

EMSL Order: 381601096  
 CustomerID: PGCS62  
 CustomerPO:  
 ProjectID:

Attn: **Karen Bowlding**  
**Prince George's County School**  
**13300 Old Marlboro Pike**  
**Upper Marlboro, MD 20772**

Phone: (301) 952-6559  
 Fax: (301) 952-0346  
 Received: 02/09/16 2:15 PM  
 Analysis Date: 2/11/2016  
 Collected: 2/5/2016

Project: **Clinton Grove**

**Clinton Grove**

### Test Report: Radon in Air Test Results

**Samples for EMSL Kit 135848**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229271	Room 313	2.8	2/5/2016	2/8/2016	60	40	Customer
381601096-0025			2:20:00 PM	7:39:00 AM			

**Sample Notes:**

229158	Room 313	2.7	2/5/2016	2/8/2016	60	40	Customer
381601096-0026			2:21:00 PM	7:40:00 AM			

**Sample Notes:**

**Summary for EMSL Kit 135848**      **Average Radon Result: 2.8 pCi/L**

**Samples for EMSL Kit 135817**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229274	Room 317	2	2/5/2016	2/8/2016	60	40	Customer
381601096-0027			2:22:00 PM	7:41:00 AM			

**Sample Notes:**

229368	Room 317	2.2	2/5/2016	2/8/2016	60	40	Customer
381601096-0028			2:23:00 PM	7:42:00 AM			

**Sample Notes:**

**Summary for EMSL Kit 135817**      **Average Radon Result: 2.1 pCi/L**

**Samples for EMSL Kit 135835**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229284	Room 315	0.6	2/5/2016	2/8/2016	60	40	Customer
381601096-0029			2:24:00 PM	7:43:00 AM			

**Sample Notes:**

229239	Room 315	0.9	2/5/2016	2/8/2016	60	40	Customer
381601096-0030			2:25:00 PM	7:44:00 AM			

**Sample Notes:**

**Summary for EMSL Kit 135835**      **Average Radon Result: 0.8 pCi/L**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>[cinnaminsonradonlab@emsl.com](mailto:cinnaminsonradonlab@emsl.com)

EMSL Order: 381601096

CustomerID: PGCS62

CustomerPO:

ProjectID:

Attn: **Karen Bowlding**  
**Prince George's County School**  
**13300 Old Marlboro Pike**  
**Upper Marlboro, MD 20772**

Phone: (301) 952-6559  
 Fax: (301) 952-0346  
 Received: 02/09/16 2:15 PM  
 Analysis Date: 2/11/2016  
 Collected: 2/5/2016

Project: **Clinton Grove****Clinton Grove****Test Report: Radon in Air Test Results****Samples for EMSL Kit 135818**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229413 381601096-0031	Room 323 - Media Center Office	0.8	2/5/2016 2:26:00 PM	2/8/2016 7:45:00 AM	60	40	Customer

**Sample Notes:**

229313 381601096-0032	Room 323 - Media Center Office	0.9	2/5/2016 2:27:00 PM	2/8/2016 7:46:00 AM	60	40	Customer
--------------------------	-----------------------------------	-----	------------------------	------------------------	----	----	----------

**Sample Notes:****Summary for EMSL Kit 135818 Average Radon Result: 0.9 pCi/L****Samples for EMSL Kit 135847**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229257 381601096-0033	Room 321	1.7	2/5/2016 2:28:00 PM	2/8/2016 7:47:00 AM	60	40	Customer

**Sample Notes:**

229242 381601096-0034	Room 321	1.8	2/5/2016 2:29:00 PM	2/8/2016 7:48:00 AM	60	40	Customer
--------------------------	----------	-----	------------------------	------------------------	----	----	----------

**Sample Notes:****Summary for EMSL Kit 135847 Average Radon Result: 1.8 pCi/L****Samples for EMSL Kit 135849**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229277 381601096-0035	Stage (MPR)	0.4	2/5/2016 2:30:00 PM	2/8/2016 7:49:00 AM	60	40	Customer

**Sample Notes:**

229178 381601096-0036	Stage (MPR)	0.2	2/5/2016 2:30:00 PM	2/8/2016 7:49:00 AM	60	40	Customer
--------------------------	-------------	-----	------------------------	------------------------	----	----	----------

**Sample Notes:****Summary for EMSL Kit 135849 Average Radon Result: 0.3 pCi/L**

The radon test was performed using a liquid scintillation radon detector/s and counted on a liquid scintillation counter using approved EPA testing protocols for Radon in Air testing. The EPA recommends fixing your home if the average of two short-term tests taken in the lowest lived-in level of the home show radon levels that are equal to or greater than 4.0pCi/L.

The EPA recommends retesting your home every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information.

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

**Report Note**



**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077  
Phone/Fax: (800) 220-3675 / (856) 786-0327  
<http://www.EMSL.com> [cinnaminsonradonlab@emsl.com](mailto:cinnaminsonradonlab@emsl.com)

EMSL Order: 381601096  
CustomerID: PGCS62  
CustomerPO:  
ProjectID:

Attn: **Karen Bowlding**  
**Prince George's County School**  
**13300 Old Marlboro Pike**  
**Upper Marlboro, MD 20772**

Phone: (301) 952-6559  
Fax: (301) 952-0346  
Received: 02/09/16 2:15 PM  
Analysis Date: 2/11/2016  
Collected: 2/5/2016

Project: **Clinton Grove**

**Clinton Grove**

**Test Report: Radon in Air Test Results**

Analyst(s)

Kathryn Lickfield (36)

*Laura Freeman* *Subash Rashat*

Laura Freeman, Interim Laboratory Manager &  
Subash Rashat, New Jersey Radiation Specialist NJ MES 10152  
or other approved signatory

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified. Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005. Subash Rashat certification #MES10152

Initial report from 02/15/2016 10:39:49

Please visit [www.radontestinglab.com](http://www.radontestinglab.com)