

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381604107
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/21/16 11:40 AM
 Analysis Date: 4/22/2016
 Collected: 4/15/2016

Project: **Glassmanor ES**

Test Site: **Glassmanor ES**
1011 Marcy Ave
Oxon Hill, MD 20745

Test Report: Radon in Air Test Results**Samples for EMSL Kit 144182**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242769	Main Office	0.3	4/15/2016	4/18/2016	70	50	Customer
381604107-0001			1:55:00 PM	7:35:00 AM			

Sample Notes:

243723	Main Office	0.3	4/15/2016	4/18/2016	70	50	Duplicate
381604107-0002			1:55:00 PM	7:35:00 AM			

Sample Notes:**Duplicate RPD = 0%****Samples for EMSL Kit 144183**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242857	Room 2	0.3	4/15/2016	4/18/2016	70	50	Customer
381604107-0003			1:56:00 PM	7:36:00 AM			

Sample Notes:**Samples for EMSL Kit 144067**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242903	Library	0.2	4/15/2016	4/18/2016	70	50	Customer
381604107-0004			1:58:00 PM	7:38:00 AM			

Sample Notes:**Samples for EMSL Kit 144068**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242981	Room 5	0.2	4/15/2016	4/18/2016	70	50	Customer
381604107-0005			1:59:00 PM	7:39:00 AM			

Sample Notes:

243766	Room 5	0.2	4/15/2016	4/18/2016	70	50	Duplicate
381604107-0006			1:59:00 PM	7:39:00 AM			

Sample Notes:**Duplicate RPD = 0%**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381604107
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/21/16 11:40 AM
 Analysis Date: 4/22/2016
 Collected: 4/15/2016

Project: **Glassmanor ES**

Test Site: **Glassmanor ES**
1011 Marcy Ave
Oxon Hill, MD 20745

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143078**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241810 381604107-0007	Room 7	0.3	4/15/2016 2:00:00 PM	4/18/2016 7:40:00 AM	70	50	Customer

Sample Notes:

241809 381604107-0008	Room 7	0.4	4/15/2016 2:00:00 PM	4/18/2016 7:40:00 AM	70	50	Duplicate
--------------------------	--------	-----	-------------------------	-------------------------	----	----	-----------

Sample Notes:**Duplicate RPD = 28.6%****Samples for EMSL Kit 144186**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242807 381604107-0009	Principal Office	0.3	4/15/2016 2:02:00 PM	4/18/2016 7:29:00 AM	70	50	Customer

Sample Notes:**Samples for EMSL Kit 143079**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241796 381604107-0010	Room 9	0.4	4/15/2016 2:04:00 PM	4/18/2016 7:30:00 AM	70	50	Customer

Sample Notes:**Samples for EMSL Kit 143085**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241648 381604107-0011	Room 19	0.5	4/15/2016 2:05:00 PM	4/18/2016 7:31:00 AM	70	50	Customer

Sample Notes:

240196 381604107-0012	Room 19	0.1	4/15/2016 2:05:00 PM	4/18/2016 7:31:00 AM	70	50	Blank
--------------------------	---------	-----	-------------------------	-------------------------	----	----	-------

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>cinnaminsonradonlab@emsl.com

EMSL Order: 381604107

CustomerID: PGCS62

CustomerPO:

ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/21/16 11:40 AM
 Analysis Date: 4/22/2016
 Collected: 4/15/2016

Project: **Glassmanor ES**

Test Site: **Glassmanor ES**
1011 Marcy Ave
Oxon Hill, MD 20745

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143086**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241614	Room 12	0.7	4/15/2016	4/18/2016	70	50	Customer
381604107-0013			2:06:00 PM	7:32:00 AM			

Sample Notes:**Samples for EMSL Kit 144076**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242996	Room 16	1.7	4/15/2016	4/18/2016	70	50	Customer
381604107-0014			2:07:00 PM	7:33:00 AM			

Sample Notes:**Samples for EMSL Kit 143076**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241622	Room 13	1.4	4/15/2016	4/18/2016	70	50	Customer
381604107-0015			2:08:00 PM	7:34:00 AM			

Sample Notes:

The radon test was performed using a liquid scintillation radon detector/s and counted on a liquid scintillation counter using approved EPA testing protocols for Radon in Air testing. The EPA recommends fixing your home if the average of two short-term tests taken in the lowest lived-in level of the home show radon levels that are equal to or greater than 4.0pCi/L.

The EPA recommends retesting your home every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information.

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Report Note



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order: 381604107

CustomerID: PGCS62

CustomerPO:

ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
Fax: (301) 952-0346
Received: 04/21/16 11:40 AM
Analysis Date: 4/22/2016
Collected: 4/15/2016

Project: **Glassmanor ES**

Test Site: **Glassmanor ES**
1011 Marcy Ave
Oxon Hill, MD 20745

Test Report: Radon in Air Test Results

Analyst(s)

Kathryn Lickfield (15)

Laura Freeman, Radon Laboratory Manager &
Peixue Ma, Ph.D, NJ Radon Measurement Specialist NJ MES
13502

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified. Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005.

Initial report from 04/28/2016 15:46:46

Please visit www.radontestinglab.com