

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381604104
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/21/16 11:39 AM
 Analysis Date: 4/23/2016
 Collected: 4/15/2016

Project: **Glen Dale Es**

Test Site: **Glen Dale Es**
6700 Glenn Dale Rd
Glenn Dale, MD 20769

Test Report: Radon in Air Test Results**Samples for EMSL Kit 142864**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242124	15	0.2	4/15/2016	4/18/2016	70	50	Customer
381604104-0001			4:48:00 PM	7:00:00 AM			

Sample Notes:

Samples for EMSL Kit 134030

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241663	26	0.3	4/15/2016	4/18/2016	70	50	Customer
381604104-0002			4:49:00 PM	7:01:00 AM			

Sample Notes:

Samples for EMSL Kit 143028

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241812	22	0.3	4/15/2016	4/18/2016	70	50	Customer
381604104-0003			4:50:00 PM	7:02:00 AM			

Sample Notes:

240068	22	0.2	4/15/2016	4/18/2016	70	50	Duplicate
381604104-0004			4:50:00 PM	7:02:00 AM			

Sample Notes:

Duplicate RPD = 40%

Samples for EMSL Kit 142965

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241793	11	0.3	4/15/2016	4/18/2016	70	50	Customer
381604104-0005			4:51:00 PM	7:04:00 AM			

Sample Notes:

240058	11	0	4/15/2016	4/18/2016	70	50	Blank
381604104-0006			4:51:00 PM	7:04:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381604104
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/21/16 11:39 AM
 Analysis Date: 4/23/2016
 Collected: 4/15/2016

Project: **Glen Dale Es**

Test Site: **Glen Dale Es**
6700 Glenn Dale Rd
Glenn Dale, MD 20769

Test Report: Radon in Air Test Results**Samples for EMSL Kit 142968**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241664 381604104-0007	18	0.3	4/15/2016 4:54:00 PM	4/18/2016 7:05:00 AM	70	50	Customer

Sample Notes:

240267 381604104-0008	18	0.1	4/15/2016 4:54:00 PM	4/18/2016 7:05:00 AM	70	50	Duplicate
--------------------------	----	-----	-------------------------	-------------------------	----	----	-----------

Sample Notes:**Duplicate RPD = 100%****Samples for EMSL Kit 142946**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242019 381604104-0009	8	0.2	4/15/2016 4:56:00 PM	4/18/2016 7:06:00 AM	70	50	Customer

Sample Notes:**Samples for EMSL Kit 142945**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
240371 381604104-0010	Kitchen	-0.1	4/15/2016 5:00:00 PM	4/18/2016 7:07:00 AM	70	50	Customer

Sample Notes:

242118 381604104-0011	Kitchen	-0.1	4/15/2016 5:00:00 PM	4/18/2016 7:07:00 AM	70	50	Blank
--------------------------	---------	------	-------------------------	-------------------------	----	----	-------

Sample Notes:**Samples for EMSL Kit 142919**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242099 381604104-0012	Main Office	0.3	4/15/2016 5:10:00 PM	4/18/2016 7:09:00 AM	70	50	Customer

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381604104
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/21/16 11:39 AM
 Analysis Date: 4/23/2016
 Collected: 4/15/2016

Project: **Glen Dale Es**

Test Site: **Glen Dale Es**
6700 Glenn Dale Rd
Glenn Dale, MD 20769

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143032**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241679	3	0.2	4/15/2016	4/18/2016	70	50	Customer
381604104-0013			5:11:00 PM	7:10:00 AM			

Sample Notes:

240031	3	0.1	4/15/2016	4/18/2016	70	50	Duplicate
381604104-0014			5:11:00 PM	7:10:00 AM			

Sample Notes:

Duplicate RPD = 66.7%

Samples for EMSL Kit 143036

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241806	5	0.2	4/15/2016	4/18/2016	70	50	Customer
381604104-0015			5:15:00 PM	7:11:00 AM			

Sample Notes:**Samples for EMSL Kit 142964**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241658	7	0.8	4/15/2016	4/18/2016	70	50	Customer
381604104-0016			5:17:00 PM	7:13:00 AM			

Sample Notes:**Samples for EMSL Kit 143029**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241814	8	0.8	4/15/2016	4/18/2016	70	50	Customer
381604104-0017			5:20:00 PM	7:15:00 AM			

Sample Notes:**Samples for EMSL Kit 142921**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242000	11A	1.4	4/15/2016	4/18/2016	70	50	Customer
381604104-0018			5:30:00 PM	7:17:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>cinnaminsonradonlab@emsl.com

EMSL Order:	381604104
CustomerID:	PGCS62
CustomerPO:	608048
ProjectID:	

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/21/16 11:39 AM
 Analysis Date: 4/23/2016
 Collected: 4/15/2016

Project: **Glen Dale Es**

Test Site: **Glen Dale Es**
6700 Glenn Dale Rd
Glenn Dale, MD 20769

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143031**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241775	12	0.7	4/15/2016	4/18/2016	70	50	Customer
381604104-0019			5:31:00 PM	7:20:00 AM			

Sample Notes:**Samples for EMSL Kit 142920**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242010	14	1.1	4/15/2016	4/18/2016	70	50	Customer
381604104-0020			5:33:00 PM	7:21:00 AM			

Sample Notes:

The radon test was performed using a liquid scintillation radon detector/s and counted on a liquid scintillation counter using approved EPA testing protocols for Radon in Air testing. The EPA recommends fixing your home if the average of two short-term tests taken in the lowest lived-in level of the home show radon levels that are equal to or greater than 4.0pCi/L. The EPA recommends retesting your home every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information.
 All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Report Note

Analyst(s)

Tiffanie Cosgrove (20)

Laura Freeman, Radon Laboratory Manager &
 Peixue Ma, Ph.D, NJ Radon Measurement Specialist NJ MES
 13502

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified. Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005.

Initial report from 04/29/2016 09:39:14

Please visit www.radontestinglab.com