Environmental Consultants and Engineers
1818 New York Avenue Suite 217
Washington, DC 20002
www.globalincusa.net

February 02, 2021

Prince Georges County
Environmental Safety Office
13306 Old Marlboro Pike
Upper Marlboro, MD 20772

Attention: Mr. Alex Baylor

RE: Indoor Air Quality Screening Report

Global Project Number: 20-064
School: Henry A Wise High School

Dear Mr. Baylor,

On January 28, 2021, Global Inc.'s (GLOBAL) team of Industrial Hygienists under the supervision of Certified Industrial Hygienist, Dr. Channa Bambaradeniya, conducted an Indoor Air Quality Screening at Henry A Wise High School located at 12650 Brooke Ln, Upper Marlboro, MD 20772.

Methodology

The IAQ evaluation included a visual assessment, sampling for non-viable mold spores in air, and measurement of comfort parameters (temperature, humidity, carbon dioxide, and carbon monoxide) in randomly selected representative locations within the building. GLOBAL's inspector conducted a walkthrough with Prince Georges County Public School (PGCPS) personnel present. Rooms were selected in a random manner throughout the building so as to prevent sampling bias.

During the visual assessment of representative locations, and when noted, GLOBAL documented those areas with suspected mold growth, water intrusions, and wet conditions that have the potential to lead to mold growth. GLOBAL also noted any unusual odors. At least one microbial air sample was collected for every 10,000 Square Feet (SF) of space in the building and the analytical results for the interior spaces were compared to an outdoor (ambient) sample collected on the same day.

Microbial samples (including a field blank for quality control) were delivered under strict chain-of-custody procedures were to Hayes Microbial Consulting - an AIHA EMPAT-certified laboratory in Midlothian, Virginia for analysis by microscopy. The sample chain-of-custody and laboratory report is attached.

GLOBAL
Environmental Consultants and Engineers
1818 New York Avenue Suite 217
Washington, DC 20002
www.globalincusa.net

Observations

The general observations in the forty indoor locations inspected are summarized in Table 1 below:

Table 1: Observations

Location	Observations
Gymnasium	No issues
Cafeteria	No issues
Room E116	No issues
Room E111	No issues
Room G108	No issues
Room 149	No issues
Room G138	No issues
Room D174	Water damage, spots on ceiling tiles
Room D171	No issues
Room D170	No issues
Room D143	No issues
Room B101	No issues
Room C105	No issues
Room A134	No issues
Room A104	No issues
Room A106	No issues
Room A206	No issues
Room A204	No issues
Room C204	No issues
Room A216	No issues
Room B205	No issues
Room B208 science lab	Spots on ceiling tiles
Media center	No issues
Room B216	No issues
Room D212	No issues
Room D214	No issues
Room C205	No issues
Room C215	No issues
Pavilion	No issues
Aerobics room E207	No issues
A347	No issues
A338	No issues

A306	No issues
A328	No issues
B301	Spots on ceiling tiles
B305	No issues
B325	No issues
D301	No issues
C305	No issues
C317	No issues

Comfort Parameter Measurements and Mold-in-Air Sample Results

The comfort parameter measurements and status of fungal ecology is summarized in Table 2.

Temperature

The American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE) have published recommendations for year-round acceptable temperatures in Standard 55-2016 (*Thermal Environmental Conditions for Human Occupancy*). The winter comfort range is 68 to 75°F and the summer comfort range is 73 to 79°F. It is important to note that ASHRAE standards are intended as a suggested guideline as opposed to a regulation. The indoor temperature readings of gymnasium, cafeteria, room 149, room G138, room D174, room D171, and room D170 were below the ASHRAE Standard for winter.

Relative Humidity (RH)

Relative humidity is a key factor for mold growth. Mold has the potential of growing on suitable surfaces with humidity levels above 60%. ASHRAE standard 62.1-2013 (*Ventilation for Acceptable Indoor Air Quality*) recommends a maximum indoor relative humidity of 65% to preclude the likelihood of condensation on cool surfaces encouraging mold growth. All the indoor relative humidity readings were below the ASHRAE maximum recommended level of 65%.

Carbon Monoxide

Carbon monoxide (CO) is a colorless and odorless gas that is produced by the incomplete combustion of carbon-containing fuels. Oil, gasoline, diesel fuels, wood, coke, and coal are the major sources of CO. All registered CO concentrations were below the EPA National Ambient Air Quality Standard (NAAQS) of 9 ppm.

Carbon Dioxide

Under conditions of maximum occupancy, ASHRAE Standard 62.1-2013, Appendix C, infers that the acceptable carbon dioxide upper limit is the prevailing outdoor carbon dioxide concentration plus 700 parts per million (ppm). On January 28, 2021, the outdoor (ambient) carbon dioxide

concentration was approximately 429 ppm so indoor concentrations should not exceed approximately 1129 ppm (700 + 429). All indoor carbon dioxide measurements were within the ASHRAE standards.

Mold-in-Air Samples

There are no definitive regulations or standardized guidelines for addressing airborne mold in an indoor setting. If building systems (ventilation, envelope) are functioning properly, the indoor fungal ecology profile should be consistent with what is encountered outdoors and the spore concentrations should be below the ambient levels. Laboratory analytical results are attached at the end of this report.

The analytical results of indoor air samples collected from all locations showed normal fungal ecology.

GLOBAL
Environmental Consultants and Engineers
1818 New York Avenue Suite 217
Washington, DC 20002
www.globalincusa.net

Table 2: Air Quality Results

Sample Location	Temp ^{0}F	RH%	CO ppm	CO2 ppm	Normal Fungal Ecology?
Standards	**ASHRAE 68 to 75°F**	**ASHRAE <65%**	**NAAQS <9**	**ASHRAE 1129**	
Ambient	29.7	36.6	0	429	Yes
Gymnasium	61.9	35.8	0	414	Yes
Cafeteria	64.9	50.0	0	438	Yes
Room E116	69.6	45.0	0	451	Yes
Room E111	69.7	46.0	0	423	Yes
Room G108	67.5	37.5	0	422	Yes
Room 149	66.6	39.0	0	427	Yes
Room G138	67.0	49.0	0	432	Yes
Room D174	64.1	47.5	0	420	Yes
Room D171	66.3	49.5	0	429	Yes
Room D170	67.3	48.4	0	426	Yes
Room D143	68.2	31.0	0	425	Yes
Room B101	70.5	33.0	0	430	Yes
Room C105	72.0	50.4	0	423	Yes
Room A134	71.7	41.2	0	422	Yes
Room A104	71.8	43.1	0	434	Yes
Room A106	71.2	49.0	0	421	Yes
Room A206	68.3	35.0	0	417	Yes
Room A204	68.2	36.4	0	418	Yes
Room C204	70.1	37.5	0	418	Yes
Room A216	70.6	48.5	0	419	Yes

GLOBAL
Environmental Consultants and Engineers
1818 New York Avenue Suite 217
Washington, DC 20002
www.globalincusa.net

Sample Location	Temp ^{0}F	RH%	CO ppm	CO2 ppm	Normal Fungal Ecology?
Standards	**ASHRAE 68 to 75°F**	**ASHRAE <65%**	**NAAQS <9**	**ASHRAE 1129**	
Room B205	73.5	41.1	0	421	Yes
Room B208 science lab	72.9	42.1	0	426	Yes
Media center	72.8	43.7	0	426	Yes
Room B216	73.0	43.2	0	419	Yes
Room D212	72.5	43.1	0	424	Yes
Room D214	71.5	42.3	0	422	Yes
Room C205	71.6	39.0	0	421	Yes
Room C215	71.3	37.0	0	417	Yes
Pavilion	73.7	35.6	0	413	Yes
Aerobics room E207	70.8	39.0	0	411	Yes
A347	69.5	45.2	0	422	Yes
A338	69.5	32.8	0	433	Yes
A306	71.3	31.2	0	421	Yes
A328	71.9	32.0	0	419	Yes
B301	70.3	32.1	0	417	Yes
B305	72.5	37.1	0	415	Yes
B325	70.5	35.5	0	426	Yes
D301	71.5	34.5	0	434	Yes
C305	70.4	38.7	0	414	Yes
C317	68.9	33.0	0	414	Yes

Environmental Consultants and Engineers
1818 New York Avenue Suite 217
Washington, DC 20002
www.globalincusa.net

Conclusions and Recommendations

Among the comfort parameters measured, the indoor temperature readings of a few locations were below the ASHRAE Standard for winter. The indoor temperature should be maintained between 68 to 75^{o}F when the school is in operation during the winter. No indoor air quality issues related to mold were found during the screening performed on January 28, 2021, and all mold samples were found to have a normal ecology for an indoor environment.

It has been our pleasure to conduct these IAQ Screening services for the Prince Georges County Public School system. If you have any questions, please feel free to contact us.

Regards,

Channa Bambaradeniya, Ph.D., CIH, CSP, CHMM
Certified Industrial Hygienist
Global, Inc.
Mobile: 443-691-0455

GLOBAL
Environmental Consultants and Engineers
1818 New York Avenue Suite 217
Washington, DC 20002
www.globalincusa.net

ATTACHMENT I

Air Sample Analytical Results and Chain-Of-Custody Form

HAYES MICROBIAL CONSULTING

#21003339

Analysis Report prepared for

Global, Inc.

1818 New York Ave.
Suite 217
Washington, DC, 20002

Phone: **(443) 691-0455**

BB203
Indoor Air Quality Assessment
PGCPS

Collected: **January 28, 2021**
Received: **January 29, 2021**
Reported: **January 29, 2021**

We would like to thank you for trusting Hayes Microbial for your analytical needs!
We received 41 samples by FedEx in good condition for this project on January 29th, 2021.

The results in this analysis pertain only to this job, collected on the stated date, and should not be used in the interpretation of any other job. This report may not be duplicated, except in full, without the written consent of Hayes Microbial Consulting, LLC..

This laboratory bears no responsibility for sample collection activities, analytical method limitations, or your use of the test results. Interpretation and use of test results are your responsibility. Any reference to health effects or interpretation of mold levels is strictly the opinion of Hayes Microbial. In no event, shall Hayes Microbial or any of its employees be liable for lost profits or any special, incidental or consequential damages arising out of the use of these test results.

Steve Hayes, BSMT(ASCP)
Laboratory Director
Hayes Microbial Consulting, LLC.

EPA Laboratory ID: VA01419

Lab ID: #188863

DPH License: #PH-0198

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap
SOP - HMC#101

Sample Number	1	HAW-0128-01		2	HAW-0128-02		3	HAW-0128-03		4	HAW-0128-04	
Sample Name	**Ambient**			**Gym E130**			**Cafeteria F100**			**E116**		
Sample Volume	75.00 liter			75.00 liter			75.00 liter			75.00 liter		
Reporting Limit	13 spores/m^3			13 spores/m^3			13 spores/m^3			13 spores/m^3		
Background	2			2			2			2		
Fragments	ND			ND			ND			ND		
Organism	**Raw Count**	**Count / m^3**	**% of Total**	**Raw Count**	**Count / m^3**	**% of Total**	**Raw Count**	**Count / m^3**	**% of Total**	**Raw Count**	**Count / m^3**	**% of Total**
Alternaria												
Ascospores	6	80	60.0%	2	27	66.7%	1	13	100.0%	2	27	100.0%
Aspergillus|Penicillium												
Basidiospores	2	27	20.0%	1	13	33.3%						
Bipolaris|Drechslera												
Chaetomium												
Cladosporium	2	27	20.0%									
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes												
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	10	134	100%	3	40	100%	1	13	100%	2	27	100%

Water Damage Indicator | Common Allergen | Slightly Higher than Baseline | Significantly Higher than Baseline | Ratio Abnormality

Collected: **Jan 28, 2021** Received: **Jan 29, 2021** Reported: **Jan 29, 2021**

Project Analyst: Ramesh Poluri, PhD P. Ramesh Date: **01 - 29 - 2021**

Reviewed By: Steve Hayes, BSMT Stephen N. Hayes Date: **01 - 29 - 2021**

HAYES MICROBIAL CONSULTING
3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112 (804) 562-3435 contact@hayesmicrobial.com

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap
SOP - HMC#101

Sample Number	5	HAW-0128-05		6	HAW-0128-06		7	HAW-0128-07		8	HAW-0128-08	
Sample Name	**E111**			**G108**			**149**			**138**		
Sample Volume	75.00 liter			75.00 liter			75.00 liter			75.00 liter		
Reporting Limit	13 spores/m³			13 spores/m³			13 spores/m³			13 spores/m³		
Background	2			1			2			2		
Fragments	ND			ND			ND			ND		
Organism	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**
Alternaria												
Ascospores	1	13	100.0%	1	13	50.0%	1	13	100.0%	2	27	66.7%
Aspergillus|Penicillium												
Basidiospores										1	13	33.3%
Bipolaris|Drechslera												
Chaetomium												
Cladosporium				1	13	50.0%						
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes												
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	1	13	100%	2	26	100%	1	13	100%	3	40	100%

Water Damage Indicator | Common Allergen | Slightly Higher than Baseline | Significantly Higher than Baseline | Ratio Abnormality

Collected: **Jan 28, 2021** Received: **Jan 29, 2021** Reported: **Jan 29, 2021**

Project Analyst: Ramesh Poluri, PhD P. Ramesh Date: **01 - 29 - 2021**

Reviewed By: Steve Hayes, BSMT Stephen N. Hayes Date: **01 - 29 - 2021**

HAYES MICROBIAL CONSULTING
3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112 (804) 562-3435 contact@hayesmicrobial.com

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap
SOP - HMC#101

Sample Number	9	HAW-0128-09		10	HAW-0128-10		11	HAW-0128-11		12	HAW-0128-12	
Sample Name	**D174**			**D171**			**D170**			**D143**		
Sample Volume	75.00 liter			75.00 liter			75.00 liter			75.00 liter		
Reporting Limit	13 spores/m³			13 spores/m³			13 spores/m³			13 spores/m³		
Background	2			2			2			1		
Fragments	ND			ND			ND			ND		
Organism	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**
Alternaria												
Ascospores	1	13	100.0%	2	27	40.0%	1	13	100.0%			
Aspergillus|Penicillium												
Basidiospores				1	13	20.0%						
Bipolaris|Drechslera												
Chaetomium												
Cladosporium				1	13	20.0%				3	40	100.0%
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes				1	13	20.0%						
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	1	13	100%	5	66	100%	1	13	100%	3	40	100%

Water Damage Indicator | Common Allergen | Slightly Higher than Baseline | Significantly Higher than Baseline | Ratio Abnormality

Collected: **Jan 28, 2021** Received: **Jan 29, 2021** Reported: **Jan 29, 2021**

Project Analyst: Ramesh Poluri, PhD P. Ramesh Date: **01 - 29 - 2021**

Reviewed By: Steve Hayes, BSMT Stephen N. Hayes Date: **01 - 29 - 2021**

HAYES MICROBIAL CONSULTING
3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112 (804) 562-3435 contact@hayesmicrobial.com

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap
SOP - HMC#101

Sample Number	13	HAW-0128-13		14	HAW-0128-14		15	HAW-0128-15		16	HAW-0128-16	
Sample Name	**B101**			**C105**			**A134**			**A104**		
Sample Volume	75.00 liter			75.00 liter			75.00 liter			75.00 liter		
Reporting Limit	13 spores/m^3			13 spores/m^3			13 spores/m^3			13 spores/m^3		
Background	1			2			2			2		
Fragments	ND			ND			ND			ND		
Organism	**Raw Count**	**Count / m^3**	**% of Total**	**Raw Count**	**Count / m^3**	**% of Total**	**Raw Count**	**Count / m^3**	**% of Total**	**Raw Count**	**Count / m^3**	**% of Total**
Alternaria												
Ascospores	1	13	50.0%	2	27	66.7%	2	27	100.0%	1	13	33.3%
Aspergillus|Penicillium												
Basidiospores				1	13	33.3%						
Bipolaris|Drechslera												
Chaetomium												
Cladosporium	1	13	50.0%							2	27	66.7%
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes												
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	2	26	100%	3	40	100%	2	27	100%	3	40	100%

Water Damage Indicator | Common Allergen | Slightly Higher than Baseline | Significantly Higher than Baseline | Ratio Abnormality

Collected: **Jan 28, 2021** Received: **Jan 29, 2021** Reported: **Jan 29, 2021**

Project Analyst: Ramesh Poluri, PhD P. Ramesh Date: **01 - 29 - 2021**

Reviewed By: Steve Hayes, BSMT Stephen N. Hayes Date: **01 - 29 - 2021**

HAYES MICROBIAL CONSULTING
3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112 (804) 562-3435 contact@hayesmicrobial.com

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap
SOP - HMC#101

Sample Number	17	HAW-0128-17		18	HAW-0128-18		19	HAW-0128-19		20	HAW-0128-20	
Sample Name	**A106**			**A206**			**A204**			**C204**		
Sample Volume	75.00 liter			75.00 liter			75.00 liter			75.00 liter		
Reporting Limit	13 spores/m^3			13 spores/m^3			13 spores/m^3			13 spores/m^3		
Background	1			2			2			2		
Fragments	ND			ND			ND			ND		
Organism	**Raw Count**	**Count / m^3**	**% of Total**	**Raw Count**	**Count / m^3**	**% of Total**	**Raw Count**	**Count / m^3**	**% of Total**	**Raw Count**	**Count / m^3**	**% of Total**
Alternaria												
Ascospores	1	13	100.0%	1	13	33.3%	1	13	100.0%	2	27	66.7%
Aspergillus|Penicillium												
Basidiospores				2	27	66.7%						
Bipolaris|Drechslera												
Chaetomium												
Cladosporium										1	13	33.3%
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes												
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	1	13	100%	3	40	100%	1	13	100%	3	40	100%

Water Damage Indicator | Common Allergen | Slightly Higher than Baseline | Significantly Higher than Baseline | Ratio Abnormality

Collected: **Jan 28, 2021** Received: **Jan 29, 2021** Reported: **Jan 29, 2021**

Project Analyst: Ramesh Poluri, PhD P. Ramesh Date: **01 - 29 - 2021**

Reviewed By: Steve Hayes, BSMT Stephen N. Hayes Date: **01 - 29 - 2021**

HAYES MICROBIAL CONSULTING
3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112 (804) 562-3435 contact@hayesmicrobial.com

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap
SOP - HMC#101

Sample Number	21	HAW-0128-21		22	HAW-0128-22		23	HAW-0128-23		24	HAW-0128-24	
Sample Name	**A216**			**B205**			**Science Lab B208**			**Media Center**		
Sample Volume	75.00 liter			75.00 liter			75.00 liter			75.00 liter		
Reporting Limit	13 spores/m³			13 spores/m³			13 spores/m³			13 spores/m³		
Background	2			2			2			2		
Fragments	ND			ND			ND			ND		
Organism	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**
Alternaria												
Ascospores	1	13	100.0%	1	13	50.0%	2	27	66.7%	1	13	100.0%
Aspergillus|Penicillium												
Basidiospores				1	13	50.0%	1	13	33.3%			
Bipolaris|Drechslera												
Chaetomium												
Cladosporium												
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes												
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	1	13	100%	2	26	100%	3	40	100%	1	13	100%

Water Damage Indicator | Common Allergen | Slightly Higher than Baseline | Significantly Higher than Baseline | Ratio Abnormality

Collected: **Jan 28, 2021** Received: **Jan 29, 2021** Reported: **Jan 29, 2021**

Project Analyst: Ramesh Poluri, PhD P. Ramesh Date: **01 - 29 - 2021**

Reviewed By: Steve Hayes, BSMT Stephen N. Hayes Date: **01 - 29 - 2021**

HAYES MICROBIAL CONSULTING
3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112 (804) 562-3435 contact@hayesmicrobial.com

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap
SOP - HMC#101

Sample Number	25	HAW-0128-25		26	HAW-0128-26		27	HAW-0128-27		28	HAW-0128-28	
Sample Name	**B216**			**D212**			**D214**			**C205**		
Sample Volume	75.00 liter			75.00 liter			75.00 liter			75.00 liter		
Reporting Limit	13 spores/m³			13 spores/m³			13 spores/m³			13 spores/m³		
Background	2			2			2			2		
Fragments	ND			ND			ND			ND		
Organism	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**
Alternaria												
Ascospores	1	13	50.0%	1	13	100.0%	3	40	100.0%	1	13	50.0%
Aspergillus|Penicillium										1	13	50.0%
Basidiospores												
Bipolaris|Drechslera												
Chaetomium												
Cladosporium	1	13	50.0%									
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes												
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	2	26	100%	1	13	100%	3	40	100%	2	26	100%

Water Damage Indicator | Common Allergen | Slightly Higher than Baseline | Significantly Higher than Baseline | Ratio Abnormality

Collected: **Jan 28, 2021** Received: **Jan 29, 2021** Reported: **Jan 29, 2021**

Project Analyst: Ramesh Poluri, PhD P. Ramesh Date: **01 - 29 - 2021**

Reviewed By: Steve Hayes, BSMT Stephen N. Hayes Date: **01 - 29 - 2021**

HAYES MICROBIAL CONSULTING
3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112 (804) 562-3435 contact@hayesmicrobial.com

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap
SOP - HMC#101

Sample Number	29	HAW-0128-29		30	HAW-0128-30		31	HAW-0128-31		32	HAW-0128-32	
Sample Name	**C215**			**Pavilion**			**Aerobic Room**			**A347**		
Sample Volume	75.00 liter			75.00 liter			75.00 liter			75.00 liter		
Reporting Limit	13 spores/m³			13 spores/m³			13 spores/m³			13 spores/m³		
Background	2			2			1			2		
Fragments	ND			ND			ND			ND		
Organism	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**
Alternaria												
Ascospores	1	13	50.0%	1	13	50.0%	1	13	100.0%	2	27	100.0%
Aspergillus|Penicillium												
Basidiospores	1	13	50.0%									
Bipolaris|Drechslera												
Chaetomium												
Cladosporium				1	13	50.0%						
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes												
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	2	26	100%	2	26	100%	1	13	100%	2	27	100%

Water Damage Indicator | Common Allergen | Slightly Higher than Baseline | Significantly Higher than Baseline | Ratio Abnormality

Collected: **Jan 28, 2021** Received: **Jan 29, 2021** Reported: **Jan 29, 2021**

Project Analyst: Ramesh Poluri, PhD P. Ramesh Date: **01 - 29 - 2021**

Reviewed By: Steve Hayes, BSMT Stephen N. Hayes Date: **01 - 29 - 2021**

HAYES MICROBIAL CONSULTING
3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112 (804) 562-3435 contact@hayesmicrobial.com

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap
SOP - HMC#101

Sample Number	33	HAW-0128-33		34	HAW-0128-34		35	HAW-0128-35		36	HAW-0128-36	
Sample Name	**A338**			**A306**			**A328**			**B301**		
Sample Volume	75.00 liter			75.00 liter			75.00 liter			75.00 liter		
Reporting Limit	13 spores/m³			13 spores/m³			13 spores/m³			13 spores/m³		
Background	2			2			2			2		
Fragments	ND			ND			ND			ND		
Organism	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**
Alternaria												
Ascospores				2	27	66.7%	1	13	50.0%	1	13	100.0%
Aspergillus|Penicillium												
Basidiospores	1	13	100.0%	1	13	33.3%	1	13	50.0%			
Bipolaris|Drechslera												
Chaetomium												
Cladosporium												
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes												
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	1	13	100%	3	40	100%	2	26	100%	1	13	100%

Water Damage Indicator | Common Allergen | Slightly Higher than Baseline | Significantly Higher than Baseline | Ratio Abnormality

Collected: **Jan 28, 2021** Received: **Jan 29, 2021** Reported: **Jan 29, 2021**

Project Analyst: Ramesh Poluri, PhD P. Ramesh Date: **01 - 29 - 2021**

Reviewed By: Steve Hayes, BSMT Stephen N. Hayes Date: **01 - 29 - 2021**

HAYES MICROBIAL CONSULTING
3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112 (804) 562-3435 contact@hayesmicrobial.com

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap
SOP - HMC#101

Sample Number	37	HAW-0128-37		38	HAW-0128-38		39	HAW-0128-39		40	HAW-0128-40	
Sample Name	**B305**			**B325**			**D301**			**C305**		
Sample Volume	75.00 liter			75.00 liter			75.00 liter			75.00 liter		
Reporting Limit	13 spores/m³			13 spores/m³			13 spores/m³			13 spores/m³		
Background	1			1			2			1		
Fragments	ND			ND			ND			ND		
Organism	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**	**Raw Count**	**Count / m³**	**% of Total**
Alternaria												
Ascospores				1	13	100.0%	1	13	50.0%			
Aspergillus|Penicillium												
Basidiospores												
Bipolaris|Drechslera												
Chaetomium												
Cladosporium							1	13	50.0%			
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes												
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	ND	ND		1	13	100%	2	26	100%	ND	ND	

Water Damage Indicator | Common Allergen | Slightly Higher than Baseline | Significantly Higher than Baseline | Ratio Abnormality

Collected: **Jan 28, 2021** Received: **Jan 29, 2021** Reported: **Jan 29, 2021**

Project Analyst: Ramesh Poluri, PhD P. Ramesh Date: **01 - 29 - 2021**

Reviewed By: Steve Hayes, BSMT Stephen N. Hayes Date: **01 - 29 - 2021**

HAYES MICROBIAL CONSULTING
3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112 (804) 562-3435 contact@hayesmicrobial.com

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap
SOP - HMC#101

Sample Number	41	HAW-0128-41
Sample Name	C317	
Sample Volume	75.00 liter	
Reporting Limit	13 spores/m^3	
Background	2	
Fragments	ND	

Organism	Raw Count	Count / m^3	% of Total
Alternaria			
Ascospores	2	27	100.0%
Aspergillus|Penicillium			
Basidiospores			
Bipolaris|Drechslera			
Chaetomium			
Cladosporium			
Curvularia			
Epicoccum			
Fusarium			
Memnoniella			
Myxomycetes			
Pithomyces			
Stachybotrys			
Stemphylium			
Torula			
Ulocladium			
Total	2	27	100%

Water Damage Indicator | Common Allergen | Slightly Higher than Baseline | Significantly Higher than Baseline | Ratio Abnormality

Collected: **Jan 28, 2021** Received: **Jan 29, 2021** Reported: **Jan 29, 2021**

Project Analyst: Ramesh Poluri, PhD P. Ramesh Date: **01 - 29 - 2021**

Reviewed By: Steve Hayes, BSMT Stephen N. Hayes Date: **01 - 29 - 2021**

HAYES MICROBIAL CONSULTING
3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112 (804) 562-3435 contact@hayesmicrobial.com

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

BB203
Indoor Air Quality Assessment
PGCPS

#21003339

Spore Trap Information

Reporting Limit	The Reporting Limit is the lowest number of spores that can be detected based on the total volume of the sample collected and the percentage of the slide that is counted. At Hayes Microbial, 100% of the slide is read so the LOD is based solely on the total volume. Raw spore counts that exceed 500 spores will be estimated.
Blanks	Results have not been corrected for field or laboratory blanks.
Background	The Background is the amount of debris that is present in the sample. This debris consists of skin cells, dirt, dust, pollen, drywall dust and other organic and non-organic matter. As the background density increases, the likelihood of spores, especially small spores such as those of Aspergillus and Penicillium may be obscured. The background is rated on a scale of 1 to 5 and each level is determined as follows: **NBD:** No background detected due to possible pump or cassette malfunction. Recollect sample. (Field Blanks will display NBD) **1 :** <5% of field occluded. No spores will be uncountable. **2 :** 5-25% of field occluded. **3 :** 25-75% of field occluded. **4 :** 75-90% of field occluded. **5 :** >90% of field occluded. Suggested recollection of sample.
Fragments	Fragments are small pieces of fungal mycelium or spores. They are not identifiable as to type and when present in very large numbers, may indicate the presence of mold amplification.
Control Comparisons	There are no national standards for the numbers of fungal spores that may be present in the indoor environment. As a general rule and guideline that is widely accepted in the indoor air quality field, the numbers and types of spores that are present in the indoor environment should not exceed those that are present outdoors at any given time. There will always be some mold spores present in "normal" indoor environments. The purpose of sampling and counting spores is to help determine whether an abnormal condition exists within the indoor environment and if it does, to help pinpoint the area of contamination. Spore counts should not be used as the sole determining factor of mold contamination. There are many factors that can cause anomalies in the comparison of indoor and outdoor samples due to the dynamic nature of both of those environments.
Water Damage Indicator Common Allergen Slightly Higher than Baseline Significantly Higher than Baseline Ratio Abnormality	**Blue:** These molds are commonly seen in conditions of prolonged water intrusion and usually indicate a problem. **Green:** Although all molds are potential allergens, these are the most common allergens that may be found indoors. **Orange:** The spore count is slightly higher than the outside count and may or may not indicate a source of contamination. **Red:** The spore count is significantly higher than the baseline count and probably indicates a source of contamination. **Violet:** The types of spores found indoors should be similar to the ones that were identified in the baseline sample. Significant increases (more than 25%) in the ratio of a particular spore type may indicate the presence of abnormal levels of mold, even if the total number of spores of that type is lower in the indoor environment than it was outdoors.
Color Coding	Fungi that are present in indoor samples at levels lower than 200 per cubic meter are not color coded on the report, unless they are one of the water damage indicators.

Shanka Dissanayake
Global, Inc.
1818 New York Ave. Suite 217
Washington, DC, 20002
(443) 691-0455

Organism Descriptions

Ascospores

Habitat: A large group consisting of more than 3000 species of fungi. Common plant pathogens and outdoor numbers become very high following rain. Most of the genera are indistinguishable by spore trap analysis and are combined on the report.

Effects: Health affects are poorly studied, but many are likely to be allergenic.

Aspergillus|Penicillium

Habitat: The most common fungi isolated from the environment. Very common in soil and on decaying plant material. Are able to grow well indoors on a wide variety of substrates.

Effects: This group contains common allergens and many can cause hypersensitivity pneumonitis. They may cause extrinsic asthma, and many are opportunistic pathogens. Many species produce mycotoxins which may be associated with disease in humans and other animals. Toxin production is dependent on the species, the food source, competition with other organisms, and other environmental conditions.

Basidiospores

Habitat: A common group of Fungi that includes the mushrooms and bracket fungi. They are saprophytes and plant pathogens. In wet conditions they can cause structural damage to buildings.

Effects: Common allergens and are also associated with hypersensitivity pneumonitis.

Cladosporium

Habitat: One of the most common genera worldwide. Found in soil and plant debris and on the leaf surfaces of living plants. The outdoor numbers are lower in the winter and often relatively high in the summer, especially in high humidity. The outdoor numbers often spike in the late afternoon and evening. Indoors, it can be found growing on textiles, wood, sheetrock, moist window sills and in HVAC supply ducts.

Effects: A common allergen, producing more than 10 allergenic antigens and a common cause of hypersensitivity pneumonitis.

Myxomycetes

Habitat: Found on decaying plant material and as a plant pathogen.

Effects: Some allergenic properties reported, but generally pose no health concerns to humans.

HAYES MICROBIAL CONSULTING

Company: Global Inc
Address: 1818 New York Ave NE Suite 217
Washington DC 20002

N

SHIP: FEDEX - BOX SO
DATE: 01-29-2021

8160 4410 5601

MOLD
21003339

Job Number: BB203	Job Name: Indoor Air Quality Assessment- PGCPS
Collector: Shanka Srivastava	
Date Collected: 01/28/21	

Mobile: 443-691-0455 | Email: Channab@globalincusa.net

Note:

Analysis Type		Analysis Description	Turnaround	Accepted Media Types
Spore Trap	S	Identification & Enumeration of Fungal Spores	24 Hour	Air Cassettes, Impact Slides
	S+	Spore Trap Analysis with Dander, Fiber, and Pollen counts	24 Hour	Air Cassettes, Impact Slides
Direct ID	D	ID & Semi-Quantative Enumeration of spores and mycelium	24 Hour	Bio-Tape, Tape, Swab, Bulk, Agar Plate
	D+	Direct Analysis with Fully Quantitative spore count	24 Hour	Bio-Tape, Tape, Swab, Bulk, Agar Plate
Culture	C1	Identification & Enumeration of Mold only	7 Day	Air Plate, Agar Plate, Swab, Bulk
	C2	Identification & Enumeration of Bacteria only	4 Day	Air Plate, Agar Plate, Swab, Bulk
	C3	Identification & Enumeration of Mold and Bacteria	7 Day	Air Plate, Agar Plate, Swab, Bulk
	C5	Coliform Screen for Sewage Bacteria	2 Day	Agar Plate, Swab, Bulk
Particle	TPA	Total Particulate Analysis, ID & Count (Does Not Include Mold)	24 Hour	Air Cassettes, Impact Slides, Bio-Tape

AP

#	Number	Sample	Analysis	Volume	Notes
1	HAW-0128-01	Ambient	S	75 L	
2	HAW-0128-02	Gym E130	S	75 L	
3	HAW-0128-03	Cafeteria F100	S	75 L	
4	HAW-0128-04	E116	S	75 L	
5	HAW-0128-05	E111	S	75 L	
6	HAW-0128-06	G108	S	75 L	
7	HAW-0128-07	149	S	75 L	
8	HAW-0128-08	138	S	75 L	
9	HAW-0128-09	D174	S	75 L	
10	HAW-0128-10	D171	S	75 L	
11	HAW-0128-11	D170	S	75 L	
12	HAW-0128-12	D143	S	75 L	
13	HAW-0128-13	B101	S	75 L	
14	HAW-0128-14	C105	S	75 L	
15	HAW-0128-15	A134	S	75 L	
16	HAW-0128-16	A104	S	75 L	

Released by:	Date:	Received By:	Date: 1/29/21

2 of 3

HAYES
MICROBIAL CONSULTING

Company: Global Inc
Address: 1818 New York Ave NE Suite 217
Washington DC 20002

N
SHIP: FEDEX - BOX SO
DATE: 01-29-2021
8160 4410 5601

MOLD
21003339

Job Number: BB203	Job Name: Indoor Air Quality Assessment- PGCPS
Collector: Shank Dinanyk	
Date Collected: 1/28/21	

Mobile: 443-691-0455 | Email: Channab@globalincusa.net
Note:

Analysis Type		Analysis Description	Turnaround	Accepted Media Types
Spore Trap	S	Identification & Enumeration of Fungal Spores	24 Hour	Air Cassettes, Impact Slides
	S+	Spore Trap Analysis with Dander, Fiber, and Pollen counts	24 Hour	Air Cassettes, Impact Slides
Direct ID	D	ID & Semi-Quantative Enumeration of spores and mycelium	24 Hour	Bio-Tape, Tape, Swab, Bulk, Agar Plate
	D+	Direct Analysis with Fully Quantitative spore count	24 Hour	Bio-Tape, Tape, Swab, Bulk, Agar Plate
Culture	C1	Identification & Enumeration of Mold only	7 Day	Air Plate, Agar Plate, Swab, Bulk
	C2	Identification & Enumeration of Bacteria only	4 Day	Air Plate, Agar Plate, Swab, Bulk
	C3	Identification & Enumeration of Mold and Bacteria	7 Day	Air Plate, Agar Plate, Swab, Bulk
	C5	Coliform Screen for Sewage Bacteria	2 Day	Agar Plate, Swab, Bulk
Particle	TPA	Total Particulate Analysis, ID & Count (Does Not Include Mold)	24 Hour	Air Cassettes, Impact Slides, Bio-Tape

#	Number	Sample	Analysis	Volume	Notes
1	HAW-0128-17	A106	S	75 L	
2	HAW-0128-18	A206	S	75 L	
3	HAW-0128-19	A204	S	75 L	
4	HAW-0128-20	C204	S	75 L	
5	HAW-0128-21	A216	S	75 L	
6	HAW-0128-22	B205	S	75 L	
7	HAW-0128-23	Science Lab B208	S	75 L	
8	HAW-0128-24	Media Center	S	75 L	
9	HAW-0128-25	B216	S	75 L	
10	HAW-0128-26	D212	S	75 L	
11	HAW-0128-27	D214	S	75 L	
12	HAW-0128-28	C205	S	75 L	
13	HAW-0128-29	C215	S	75 L	
14	HAW-0128-30	Pavilion	S	75 L	
15	HAW-0128-31	Aerobic Room	S	75 L	
16	HAW-0128-32	A347	S	75 L	

Released by:	Date:	Received By:	Date:
		TP	1/29/21

3 of 3

HAYES MICROBIAL CONSULTING

Company: Global Inc
Address: 1818 New York Ave NE Suite 217
Washington DC 20002

N

SHIP: FEDEX - BOX SO
DATE: 01-29-2021

8160 4410 5601

MOLD

21003339

Job Number: BB203	**Job Name:** Indoor Air Quality Assessment- PGCPS
Collector: Shanka Dissanayak	**Mobile:** 443-691-0455
Date Collected: 01/28/21	**Email:** Channab@globalincusa.net
	Note:

Analysis Type		Analysis Description	Turnaround	Accepted Media Types
Spore Trap	S	Identification & Enumeration of Fungal Spores	24 Hour	Air Cassettes, Impact Slides
	S+	Spore Trap Analysis with Dander, Fiber, and Pollen counts	24 Hour	Air Cassettes, Impact Slides
Direct ID	D	ID & Semi-Quantative Enumeration of spores and mycelium	24 Hour	Bio-Tape, Tape, Swab, Bulk, Agar Plate
	D+	Direct Analysis with Fully Quantitative spore count	24 Hour	Bio-Tape, Tape, Swab, Bulk, Agar Plate
Culture	C1	Identification & Enumeration of Mold only	7 Day	Air Plate, Agar Plate, Swab, Bulk
	C2	Identification & Enumeration of Bacteria only	4 Day	Air Plate, Agar Plate, Swab, Bulk
	C3	Identification & Enumeration of Mold and Bacteria	7 Day	Air Plate, Agar Plate, Swab, Bulk
	C5	Coliform Screen for Sewage Bacteria	2 Day	Agar Plate, Swab, Bulk
Particle	TPA	Total Particulate Analysis, ID & Count (Does Not Include Mold)	24 Hour	Air Cassettes, Impact Slides, Bio-Tape

AD

#	Number	Sample	Analysis	Volume	Notes
1	HAW-0128-33	A338	S	75 L	
2	HAW-0128-34	A306	S	75 L	
3	HAW-0128-35	A328	S	75 L	
4	HAW-0128-36	B301	S	75 L	
5	HAW-0128-37	B305	S	75 L	
6	HAW-0128-38	B325	S	75 L	
7	HAW-0128-39	D301	S	75 L	
8	HAW-0128-40	C305	S	75 L	
9	HAW-0128-41	C317	S	75 L	
10					
11					
12					
13					
14					
15					
16					

Released by:	Date:	Received By:	Date: 1/29/21