

November 2, 2023

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
JOHN H. BAYNE ES
MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
11292939	102	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	< 0.3	2023-11-02
11292943	103	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	< 0.3	2023-11-02
11292946	103	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	< 0.3	2023-11-02
11292935	106	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	< 0.3	2023-11-02
11292941	107	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	0.5 ± 0.3	2023-11-02
11292937	109	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	0.6 ± 0.3	2023-11-02
11292948	112	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	< 0.3	2023-11-02
11292945	114	2023-10-27 @ 3:00 pm	2023-10-30 @ 2:00 pm	< 0.3	2023-11-02
11292940	116	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	< 0.3	2023-11-02
11292953	116	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	0.5 ± 0.3	2023-11-02
11292944	HEALTH ROOM	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	0.6 ± 0.3	2023-11-02
11292930	MULTIPURPOSE ROOM BY KITCHEN	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	0.6 ± 0.3	2023-11-02
11292938	MULTIPURPOSE ROOM BY STAGE	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	0.5 ± 0.3	2023-11-02
11292929	PRINCIPALS OFFICE	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	< 0.3	2023-11-02
11292947	PRINCIPALS OFFICE	2023-10-27 @ 2:00 pm	2023-10-30 @ 2:00 pm	< 0.3	2023-11-02

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498